2741360/2024/O/o CAO/CORE/PRYJ

केन्द्रीय रेल विद्युतीकरण संगठन
Central Organisation For Railway Electrification
1, Nawab Yusuf Road, Civil Lines, Prayagraj – 211001
Website: www.core.indianrailways.gov.in
Email: dyceemp@gmail.com

No. : CORE-HQ0ELEC(MP)/66/2024 **Date : 18-01-2024**

All Approved Vendors for
Raised Register Arm Adjuster (RI-2432)

SUB : Development of Raised Register Arm Bent Adjuster (R.I. : 2432-1) as per RDSO drawing no. TI/DRG/OHED/RRABA/00001/23/0.

REF : RDSO letter no. RDSO-TI0LKO(OHE)/11/2020 dated 09-01-2024.

****

Vide letter under reference above, RDSO has directed to develop Raised Register Arm Bent Adjuster (RI - 2432-1) as per RDSO drawing no. TI/DRG/OHED/RRABA /00001/23/0.

Therefore, all approved vendors for Raised Register Arm Adjuster (RI-2432) are hereby advised to develop prototype of the above mentioned fitting and submit your internal test report to this office within 15 days from the date of issue of this letter.

A copy of above mentioned RDSO drawing is enclosed herewith for reference.

DA :- As Above.

18/1/24

(Kalyan Singh)
Dy. Chief Electrical Engineer (MP)
CORE / Prayagraj

Scanned with CamScanner

2741360/2024/O/o CAO/CORE/PRYJ

केन्द्रीय रेल विद्युतीकरण संगठन
Central Organisation For Railway Electrification
1, Nawab Yusuf Road, Civil Lines, Prayagraj – 211001
Website: www.core.indianrailways.gov.in
Email: dyceemp@gmail.com

No. : CORE-HQ0ELEC(MP)/66/2024 **Date : 04-03-2024**

All Approved Vendors for
Raised Register Arm Adjuster (RI-2432)

SUB : Reminder for Development of Raised Register Arm Bent Adjuster (R.I. : 2432-1) as per RDSO drawing no. TI/DRG/OHED/RRABA/00001/23/0.

REF : 1) RDSO letter no. RDSO-TI0LKO(OHE)/11/2020 dated 09-01-2024.
2) This office letter no. CORE-HQ0ELEC(MP)/66/2024 Date : 04-03-2024

****

Vide letter under REF (1) above, RDSO directed to develop Raised Register Arm Bent Adjuster (RI - 2432-1) as per RDSO drawing no. TI/DRG/OHED/RRABA /00001/23/0.

This office advised all approved vendors for Raised Register Arm Adjuster (RI-2432) to develop prototype of the above mentioned fitting and submit your internal test report to this office.

Till date no response has been received from your side. Therefore, your firms are again advised to develop the above mentioned fitting and submit your internal testing reports to this office at the earliest.

A copy of above mentioned RDSO drawing is enclosed herewith for reference.

DA :- As Above.

04.3.24

(Kalyan Singh)
Dy. Chief Electrical Engineer (MP)
CORE / Prayagraj

Scanned with CamScanner